



## DMW-R100 Voltage values

These measurements can be taken from any point using chassis as DC -ve ( black wire on the voltmeter) although the best place to take all the measurements is the DC-102 PCB.

The colour refer to the cables, where there are two different values for the same colour the connector number is given. This number can be found printed on the DC-102 next to its corresponding connector.

Cable Colour	Connector #	Voltage
Black		0V ( D-Gnd)
Grey		0V ( A-Gnd)
Red		+5V
Brown		+3.3V
Brown	CN114 (Pin4)	+2.9V
Violet		+48V
Blue	CN-118	-12V
Yellow	CN-118	+12V
Blue	CN-113	-15V
Yellow1	CN-113	+15
Orange		+12(Unreg)

